

ANNEXURE VII  
PERFORMANCE REPORT OF WORKS

PART I

(To be filled in by the contractor in duplicate in respect of each work cost of which falls within the range prescribed for eligibility as per para 19 of enlistment read with Table -I. One copy be submitted to Reporting Officer and other, containing acknowledgement of receipt and seal of office of reporting officer, be submitted to Secretary (CRB))

1. Period: 15-2-10 To 14-6-10
2. Name & Address of contractor: Sh Harinder Singh, Sr Extension -1, Kirti Nagar, N.D-15
3. Class, Category and Enlistment No.: Class-II (B & R) DDA
4. Name & address of enlisting authority: Secretary, CRB, DDA
5. Name of Work: DDA Millennium Park along Ring Road between ISBT Samikata Khan & Bheem Road. SH: Rock Garden (Supply of natural Stone at Shanti Stupa)
6. Agreement No.: 97/EE/SED-II/DDA/2009-10
7. Name & Address of Division: SED-II/DDA/Vikram Sarabhai/INA/N.D-23

Sl.	Item	
8.1	Estimated Cost/Tender amount	Rs 5,78,931/- + Rs 64,17,080/-
8.2	Stipulated date of Commencement & Completion	15-2-10 & 14-6-10
8.3	Percentage progress with date/actual date of completion	14-6-10
8.4	Gross amount of final bill/work done	Rs 70,08,040/-
8.5	Amount of compensation levied, if any	N.A.
8.6	Amount of reduced rate items, if any	N.A.
8.7	Did the contractor go for arbitration?	N.A.
8.8	If yes, total amount claimed and amount awarded	N.A.

Harinder Singh  
Signature of the contractor

PART II

(To be filled by the department)

- 9.0 Certified that details given by the contractor in Part - I have been verified and found to be correct/have been corrected wherever necessary.  
Delay is partly /not/ fully attributable to contractor.

Signature of Divisional/Sub Divisional Engineer

- 10.0 Note : After submission of Annexure VII by contractor, reporting officer shall write the Report and forward to Reviewing officer within a week's time. Reviewing officer shall then forward the report to the Enlisting authority within a week's time.

Class	I	II	III	IV	V
Reporting Officer	E.E	E.E	EE	AE	AE
Reviewing Officer	S.E	S.E	SE	EE	EE

Note: The Performance Report shall be countersigned by the respective Chief Engineer also, if the cost of the Work exceeds Rs. One Crore.

155

Part - III (Serial 1 to 6 are repeat information for proper linkage)

1. Period: 15.2.10 To 14.6.10  
2. Name & Address of contractor: Sh. Harinder Singh, G-Extension 1, Kirti Nagar, N. Delhi-15  
3. Class, Category and Enlistment No.: Class-III, (B & R) DDA  
4. Name & address of enlisting authority: Secy, CRB, DDA  
5. Name of Work: Sh. Rock Garden (Supply of natural Stone at Shanti Stupa)  
6. Name & Address of D.D.A. Division: EE/SED-11/DDA/2009-10  
7. Agmt no 97/EE/SED-11/DDA/2009-10

10.1	Quality of work	Outstanding/Very good/Good/Satisfactory/Poor
10.2	Comments on capability of contractor	
10.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory/Poor
10.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory/Poor
10.2.3	Mobilizations of T&P	Outstanding/Very good/Good/Satisfactory/Poor
10.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/Poor
10.2.5	General behavior	Outstanding/Very good/Good/Satisfactory/Poor

10.2.6 General Remarks\* outstanding/Very good/Good/Satisfactory/Poor

Executive Engineer  
Reporting Officer (Designation and Address)  
South Eastern Division  
O.D.A. Vikas Sadan, N. Delhi

11.1	Quality of work	outstanding/Very good/Good/Satisfactory/Poor
11.2	Comments on capability of contractor	
11.2.1	Technical proficiency	outstanding/Very good/Good/Satisfactory/Poor
11.2.2	Financial soundness	outstanding/Very good/Good/Satisfactory/Poor
11.2.3	Mobilizations of T&P	outstanding/Very good/Good/Satisfactory/Poor
11.2.4	Mobilizations of man power	outstanding/Very good/Good/Satisfactory/Poor
11.2.5	General behavior	outstanding/Very good/Good/Satisfactory/Poor

11.2.6. General Remarks\* outstanding/Very good/Good/Satisfactory/Poor

29/11/11  
Reviewing Officer (Designation & Address)



(15)

## ANNEXURE VII PERFORMANCE REPORT OF WORKS

### PART I

(To be filled in by the contractor in duplicate in respect of each work cost of which falls within the range prescribed for eligibility as per para 19 of enlistment read with Table -I. One copy be submitted to Reporting Officer and other, containing acknowledgement of receipt and seal of office of reporting officer, be submitted to Secretary (CRB))

1. Period: 4-3-07 TO 22-7-08
2. Name & Address of contractor: Sh Harinder Singh, G-Extension 1, Kirti Nagar, N.D-15
3. Class, Category and Enlistment No.: Class-III (BQR) DDA
4. Name & address of enlisting authority: Secretary CRB, DDA
5. Name of Work: Spl. repair & renovation of Vikas Sadan - SH: Renovation of Toilets # B-Block, Vikas Sadan
6. Agreement No.: 62/EE/SEB-II/DDA/2006-07
7. Name & Address of Division: SEB-II/DDA/Vikas Sadan / INA / N.D-23

Sl.	Item	
8.1	Estimated Cost/Tender amount	Rs 23,38,013/- to Rs 24,80,731/-
8.2	Stipulated date of Commencement & Completion	4-3-07 to 3-12-07
8.3	Percentage progress with date/actual date of completion	22-7-08
8.4	Gross amount of final bill/work done	Rs 23,03,383/-
8.5	Amount of compensation levied, if any	N.A.
8.6	Amount of reduced rate items, if any	N.A.
8.7	Did the contractor go for arbitration?	NO
8.8	If yes, total amount claimed and amount awarded	N.A.

Harinder Singh  
Signature of the contractor

### PART II

(To be filled by the department)

9.0 Certified that details given by the contractor in Part - I have been verified and found to be correct/have been corrected wherever necessary.

Delay is partly /not/ fully attributable to contractor.

Signature of Divisional/Sub Divisional Engineer

10.0 Note : After submission of Annexure VII by contractor, reporting officer shall write the Report and forward to Reviewing officer within a week's time. Reviewing officer shall then forward the report to the Enlisting authority within a week's time.

Class	I	II	III	IV	V
Reporting Officer	E.E	E.E	EE	AE	AE
Reviewing Officer	S.E	S.E	SE	EE	EE

Note: The Performance Report shall be countersigned by the respective Chief Engineer also, if the cost of the Work exceeds Rs. One Crore.

Part - III (Serials 1 to 6 are repeat information for proper linkage)

1. Period:

4-3-07 To 22-7-08

2. Name & Address of contractor: Sh Harinder Singh, G-Extension, 1, Kirti Nagar, N.D-15

3. Class, Category and Enlistment No.: Class III (BR R) DDA

4. Name & address of enlisting authority: Secy, CRB, DDA

5. Name of Work: Spl. repair & renovation of Vikas Sadan - Spl. Renovation of toilets of B-Block, Vikas Sadan.

6. Name & Address of D.D.A. Division: EE/SED-11/DDA/2006-07

7. Agent No 62/EE/SED-11/DDA/2006-07

10.1	Quality of work	Outstanding/Very good/Good/Satisfactory/Poor
10.2	Comments on capability of contractor	
10.2.1	Technical proficiency	Outstanding/Very good/Good/Satisfactory/Poor
10.2.2	Financial soundness	Outstanding/Very good/Good/Satisfactory/Poor
10.2.3	Mobilizations of T&P	Outstanding/Very good/Good/Satisfactory/Poor
10.2.4	Mobilizations of man power	Outstanding/Very good/Good/Satisfactory/Poor
10.2.5	General behavior	Outstanding/Very good/Good/Satisfactory/Poor

10.2.6 General Remarks\*

outstanding/Very good/Good/Satisfactory/Poor

Reporting Officer (Designation and Address)

Executive Engineer  
South Eastern Division-XI  
D.D.A. Vikas Sadan, N.D-15

11.1	Quality of work	outstanding/Very good/Good/Satisfactory/Poor
11.2	Comments on capability of contractor	
11.2.1	Technical proficiency	outstanding/Very good/Good/Satisfactory/Poor
11.2.2	Financial soundness	outstanding/Very good/Good/Satisfactory/Poor
11.2.3	Mobilizations of T&P	outstanding/Very good/Good/Satisfactory/Poor
11.2.4	Mobilizations of man power	outstanding/Very good/Good/Satisfactory/Poor
11.2.5	General behavior	outstanding/Very good/Good/Satisfactory/Poor

11.2.6 General Remarks\*

outstanding/Very good/Good/Satisfactory/Poor

Reviewing Officer (Designation & Address)